

ALPHANUMERIC INDEX — CROSS-REFERENCE (Continued)

Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number	Industry Part Number	Motorola Direct Replacement	Motorola Similar Replacement	Page Number
2SA861		MPS-U51	3-1058	2SB522		TIP42A	3-1083
2SA877		2N5876	3-120	2SB523		2N5193	3-89
2SA878		MJ15002	3-710	2SB524		2N5194	3-89
2SA882		MJ15002	3-710	2SB526		2N4920	3-75
2SA887		2N4919	3-75	2SB527		2N4920	3-75
2SA897		MPS-U55	3-1062	2SB528		2N4920	3-75
2SA898		MJE350	3-880	2SB529		2N5193	3-89
2SA899		MJE350	3-880	2SB530		MJ15002	3-710
2SA900		MJE210	3-866	2SB531		MJ15016	3-9
2SA907		MJ15016	3-9	2SB532		MJ15016	3-9
2SA908		MJ15002	3-710	2SB536		TIP32C	3-1073
2SA909		MJ15003	3-713	2SB537		TIP32C	3-1073
2SA922		2N4918	3-75	2SB539		MJ15002	3-710
2SA939		MJE350	3-880	2SB541		MJ15002	3-710
2SA940		MJE15031	3-972	2SB546		MJE15031	3-972
2SA949		MJE15031	3-972	2SB547		MJE15031	3-972
2SA957		MJE15031	3-972	2SB548		2N4920	3-75
2SA958		MJE15031	3-972	2SB549		2N4920	3-75
2SA962		MPS-U55	3-1062	2SB552		MJ15023	3-723
2SA963		MJE171	3-862	2SB553		2N6107	3-151
2SA965		MJE15029	3-972	2SB554		MJ15023	3-723
2SA966		TIP32	3-1073	2SB555		MJ15012	3-716
2SA968		MJE15031	3-972	2SB556		MJ15012	3-716
2SA969		MJE15031	3-972	2SB557		MJ15002	3-710
2SA971		2N6609	3-52	2SB558		2N5880	3-123
2SA980		2N5880	3-123	2SB559		2N4918	3-75
2SA981		MJ15002	3-710	2SB565		2N6125	3-154
2SA982		MJ15002	3-710	2SB566		TIP32C	3-1073
2SB1020		2N6042	3-139	2SB567		MJE15031	3-972
2SB1022		2N6040	3-139	2SB568		MJE15031	3-972
2SB1024		TIP127	3-1098	2SB569		2N6034	3-135
2SB1047L		MJD117-1	3-816	2SB570		2N6035	3-135
2SB1047S		MJD117	3-816	2SB571		2N6036	3-135
2SB1072L		MJD6036-1	3-848	2SB572		2N5193	3-89
2SB1072S		MJD6036	3-848	2SB573		2N5194	3-89
2SB1179		MJD6036-1	3-848	2SB574		2N5195	3-89
2SB1179A		MJD6036-1	3-848	2SB575		2N5193	3-89
2SB1180		MJD127-1	3-822	2SB576		2N5194	3-89
2SB1180A		MJD127-1	3-822	2SB577		2N5195	3-89
2SB1201		MJD45H11-1	3-808	2SB578		MJE2955	3-904
2SB1202		MJD45H11-1	3-808	2SB579		MJE2955	3-904
2SB1203		MJD45H11-1	3-808	2SB580		MJE2955	3-904
2SB1204		MJD45H11-1	3-808	2SB581		MJE2955	3-904
2SB1205		MJD210-1	3-832	2SB582		MJE6040	3-139
2SB1214		MJD6036-1	3-848	2SB583		MJE6041	3-139
2SB1215		MJD45H11-1	3-808	2SB584		MJE6041	3-139
2SB1216		MJD45H11-1	3-808	2SB585		2N6053	3-147
2SB502		2N3741	3-41	2SB586		2N6054	3-147
2SB503		2N3741	3-41	2SB587		2N6050	3-143
2SB506		MJ15016	3-9	2SB588		2N6051	3-143
2SB507		2N6125	3-154	2SB589		2N6052	3-143
2SB509		TIP32C	3-1073	2SB595		TIP42C	3-1083
2SB511		TIP32	3-1073	2SB596		TIP32C	3-1073
2SB513		TIP32C	3-1073	2SB600		MJ15012	3-716
2SB514		TIP32A	3-1073	2SB604		TIP32C	3-1073
2SB515		TIP32A	3-1073	2SB628		MJE15031	3-972
2SB518		MJ15016	3-9	2SB630		MJE15031	3-972
2SB519		MJ15016	3-9	2SB631		2N4920	3-75
2SB520		MJ15016	3-9	2SB632		2N4918	3-75
2SB521		TIP42A	3-1083	2SB633		TIP42C	3-1083

*Consult Motorola if a direct replacement is necessary.